

MATERIAL SAFETY DATA SHEET

RAMCO INSULATION, INC
2021 ROOSEVELT, JOPLIN, MISSOURI 64804
TELEPHONE 417-781-8855 FAX 417-781-9192

SECTION IPRODUCT NAME: 1-MWP, 1-GP/FF, 1-FW, MW, V-16, 1-V, 1-GPFORMULA: NOT APPLICABLEPRODUCT TYPE: THERMOKOTE CEMENTSNFPA RATING: 1-0-0-0CHEMICAL FAMILY: NOT APPLICABLEDOT NO: NOT REGULATEDSECTION IIPRODUCT HAZARDOUS INGREDIENTS

<u>MATERIAL</u>	<u>TLV-TWA</u>	<u>CAS=</u>	<u>PERCENT</u>
Mineral Wool Fiber	10 mg. M total 5 mg. M respirable	65997-17-3	25-35
Bentonite Collodial Clay	10 mg. M total 5 mg. M respirable	1302-78-9	15-25
Ball Clay	10 mg. M total 5 mg. M respirable	1318-74-7	15-25
Portland Cement	10 mg. M total 5 mg. M respirable	65997-15-1	25-35
Muscovite	10 mg. M total 5 mg. M respirable	12001-26-2	10-20
Pyrophyllite	15 mg. M total 5 mg. M respirable	12269-78-2	5-15
Fly Ash	10 mg. M total 5 mg. M respirable	14808-60-7	5-15
Microfil	10 mg. M total 5 mg. M respirable	93763-70-3	5-10
Cellulose	Not listed	65996-61-4	5-10
Vermiculite	Not listed	1318-00-9	15-25
Rust Inhibitor (Trade Secret)	10 mg. M total 5 mg. M respirable	-----	<5

Note: International Agency for Research on Cancer (IARC) has classified crystalline silica in the category of Group 1
(DOES NOT CONTAIN ASBESTOS)

SECTION III HAZARDS
INFORMATION

This product contains crystalline silica. Prolonged exposure to dust may cause silicosis, a progressive pneumoconiosis, or other respiratory diseases. International Agency for Research on Cancer (IARC) has classified crystalline silica as Group 1. The agency states there is sufficient evidence of carcinogenicity in humans. Reference: IARC Monograph 68.

Dust from product at any stage of its use or during tear-out after service may, especially on long term exposure, lead to lung disease unless respiratory protection is employed. NIOSH approved respirators should be worn any time that refractories are torn out after service. While a respiratory hazard and/or nuisance dust may exist from the product itself, other foreign substances may warrant additional precautions during tear-out and disposal.

SECTION IV
FIRE AND EXPLOSION HAZARD DATA

FLASH POINT: Non-Combustible

EXTINGUISHING MEDIA: Material compatible with CO water or dry chemical extinguishing media.

SPECIAL FIRE FIGHTING PROCEDURES: None

UNUSUAL FIRE AND EXPLOSION HAZARDS: None

SECTION V
FIRST AID AND HEALTH HAZARD DATA

EFFECT OF OVEREXPOSURE:

<u>EYES:</u>	ACUTE: May cause irritation. CHRONIC: None known.
<u>SKIN:</u>	ACUTE: May cause skin irritation. CHRONIC: None known.
<u>INHALATION:</u>	ACUTE: May cause upper respiratory irritation. CHRONIC: Prolonged irritation of mineral wool dust may reduce lung function.

EFFECTS OF OVEREXPOSURE:

INGESTION: ACUTE: CONSULT A PHYSICIAN IMMEDIATELY.

EMERGENCY AND FIRST AID PROCEDURES:

EYES: Immediately rinse eyes with plenty of water until irritation stops.

SKIN: Wash frequently with soap and water to minimize irritation.

INHALATION: Remove to fresh air. Remove fibers and dust from nose and drink water to clear throat.

INGESTION: Consult a physician immediately.

NOTE: Should any of the above conditions persist, consult a physician.

SECTION VI
ACCIDENTAL RELEASE MEASURES

SPILLS: Avoid creating dust, use a vacuum or wet clean-up to minimize dust.

WASTE DISPOSAL: Mineral wool fiber products are generally classified as a non-hazardous waste and may be disposed of in a non-critical landfill. Always check all local, state and federal regulations.

SECTION VII HANDLING
AND STORAGE

Store in dry area. Product is non-flammable.

SECTION VIII
EXPOSURE CONTROLS AND PERSONAL PROTECTION

RESPIRATORY PROTECTION: Wear NIOSH/MSHA approved respirators.

VENTILATION: Use sufficient ventilation (natural or mechanical) while handling this material in a dry state, to maintain airborne dust levels below TLV.

EYE PROTECTION: Safety glasses or goggles should be worn when materials are being handled.

GENERAL INFORMATION: Use waterproof or rubber gloves to protect hands. Clothing should be long sleeved, loose fitting and a cap should be worn. Wash all work clothing separate from other clothing to prevent possible migration of mineral wool fiber and dust to other clothes.
